


# PMA-6000/CMA-6000

This guide illustrates how to assemble the corner mount adapter and pole mount adapter.  
Check the letter of the alphabet assigned to each adapter and tighten the screws in the corresponding holes to assemble the adapter.



A-A-A-A(M5 PAM)  
IPN6602HD

B-B-B(B(M4 PAM)  
IPN6702HD

C-C-C(M4 PAM)  
IPN6802HD